

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

| | | | |
|-----------------------|---|------|-----------------------------|
| CAMPAIGN No. | Gai-2481 | DATE | May 17 th , 2017 |
| MANUFACTURER | BMW (Japanese Importer: BMW Group Japan Corp.) | | |
| DESCRIPTION OF DEFECT | The fault involves the oil cooler pipes on the engine cooling system. Due to the inappropriate production, the cooler pipes might not have been inserted into the sleeves appropriately, thus preventing proper crimping. In case of keep driving under this condition, engine oil might leak, and in worst case, leaked oil might drop onto the front brake disks, which leads to decreased braking force. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|-------------------|---------------------|-------------------|
| CBA-7H66 | BMW M760Li xDrive | 2016 - 2017 | 14 |
| | | TOTAL | 14 |