

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2479	DATE	May 24, 2017
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>There are irregularities in the mix ratio of the igniting agent in some airbag units or belt tensioners which could lead to the airbags/belt tensioners not triggering in the event of an accident.</p> <p>The airbags and/or belt tensioners affected must be replaced on the corresponding vehicles.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-4GCREB	A6 Allroad	2017	3
ABA-4GCREC	A7 SB 3.0Tq	2017	1
ABA-4GCRES	A6 3.0Tq	2017	1
ABA-4GCTGA	S6	2017	1
ABA-4GCWUS	RS6 Avant	2017	1
ABA-4GCYPC	A7 SB 2.0Tq	2017	2
ABA-4GCYPS	A6 2.0Tq/ A6 Avant 2.0Tq	2017	4
ABA-4HCTGF	A8 4.0Tq	2017	1
ABA-4HDDTF	S8 plus	2017	1
ABA-8WCVK	A4 2.0T	2017	20
ABA-8WCVN	A4 1.4T	2017	28
ABA-8WCYRA	A4 Allroad	2017	25
DBA-8WCYRF	A4 2.0Tq	2017	38
		Total	126