

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4058	DATE	June 2, 2017
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>Since the hose between the hydrostatic transmission pump and the motor is not installed as instructed on the drawing, it interferes with the brake hose connected to the rear wheel brake valve on some machines. As a result, the hose from the hydrostatic transmission or the brake hose are worn and oil may leak because of vibration during operation. In the worst case, the machine is disabled to travel or its braking distance increases.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDR-WA122	「WA270-7」	2014 to 2017	345
		TOTAL	345