

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2499	DATE	June 26 th , 2017
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to incorrect processing on the inside of the instrument panel, the necessary opening line for the front passenger airbag might not be milled correctly. Thus, in case of a collision accident where deployment of the front passenger airbag is necessary, the opening of the airbag cover may not function properly increasing the risk of injury.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-HS15	BMW X1 xDrive 18i	2016	1,361
LDA-HT20	BMW X1 xDrive 18d	2016 - 2017	2,064
DBA-HS20	BMW X1 xDrive 20i	2016 - 2017	471
	BMW X1 xDrive 25i	2016 - 2017	84
		TOTAL	3,980