

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2442	DATE	June 29, 2017
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>A leak can occur on the flange of the fuel delivery unit/fuel filter. Fuel can escape and create a corresponding odour. If cracks are already visible, the flange is renewed.</p> <p>A protective film must be stuck onto the flange of the fuel delivery unit/fuel filter to protect the flange from external damage.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-4LBARA	Q7 4.2q Air suspension	2007 – 2010	470
ABA-4LBARS	Q7 4.2q	2008 – 2010	49
ABA-4LBHKA	Q7 3.6q Air suspension	2007 – 2009	331
ABA-4LBHKS	Q7 3.6q	2007 – 2010	753
ABA-4LCJTL	Q7 3.0Tq Air suspension	2011 – 2012	222
ABA-4LCJTS	Q7 3.0Tq	2011 – 2012	997
ABA-8RCALF	Q5 3.2q	2009 – 2012	394
ABA-8RCDNF	Q5 2.0Tq	2009 – 2012	4,230
ABA-8RCNCF		2013 – 2017	5,000
ABA-8RCTVF	Q5 3.0Tq	2013 – 2014	205
ABA-8RCTXF	SQ5	2014 – 2017	1,151
DAA-8RCHJF	Q5 Hyblid	2013 – 2014	166
		Total	13,968