

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-2506	Date	June 29, 2017
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	A flasher blink speed may be slow. Then, it brings non conformance against article 41st.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-HRDL	「226D」	2016	5
YDN-FULL	「259D」	2016	13
		TOTAL	18