

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2518	DATE	July 31, 2017
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>Tolerances for the belt tensioners on the rear seat belts were occasionally exceeded during manufacture. Due to a faulty connection, parts of the pyrotechnical system could become dislodged on deployment in an accident and enter the vehicle interior, putting the occupants at risk of injury.</p> <p>The affected seat belt components must be replaced on the affected vehicles.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-8FNDNF	A5 Cabriolet 2.0 Tq	2017	4
		Total	4