

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4088	DATE	Aug. 1 2017
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty dump trucks, the fuel tank mounting bracket at the rear of the vehicle is installed in a state of interfering with a rivet in the vehicle frame side surface. If the truck continues to be used in this condition, the fastening bolts of the bracket may loosen and cause cracks in the bracket. In the worst case, the fuel tank or fuel piping will be damaged, resulting in a fuel leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FV70GX	「FUSO SUPER GREAT」	2017	1
		TOTAL	1