

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4092	DATE	AUG. 4, 2017
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to an improper manufacturing process of the steering rack gear, it may lack sufficient strength, causing it to break. In the worst case, this may result in loss of steering.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-VM4	「LEVORG」	2017	165
DBA-VMG		2017	40
DBA-VAG	「WRX」	2017	6
		TOTAL	211