

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2526	DATE	August 29 th , 2017
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The fault involves the oil cooler pipes (left radiator feed) on the engine cooling system. Due to the inappropriate production, it is possible that a wrong type of pipe with insufficient reinforcement has been used for assembly. In this case, a rip on the pipe cannot be excluded, where the engine oil might spill out. In worst case, spilled oil might drop onto the front brake disks, which leads to decreased braking force.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-7H66	BMW M760Li xDrive	2016 - 2017	34
		TOTAL	34