

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2532	DATE	August 31, 2017
MANUFACTURER	General Motors LLC		
DESCRIPTION OF DEFECT	<p>General Motors has decided that Cadillac CTS right hand drive (RHD) equipped with 3.0L V6 engines, and Cadillac CTS equipped with 3.6L V6 engines fail to conform with the Road Vehicle Act by JMLIT (Japan Ministry of Land, Infrastructure, Transport and Tourism).</p> <p>One of the two brake lines to the brake master cylinder could sever and leak. This could affect either brake circuit (left front and right rear; right front and left rear) of the brake system. With this condition the customer will experience an increase in brake pedal travel along with a reduction in vehicle deceleration vs. pedal force capability. Once sufficient brake fluid is lost, a brake warning light will warn the customer of low brake fluid in the master cylinder reservoir.</p> <p>The customer could smell and/or see smoke and there is a possibility of a fire due to the brake fluid leaking onto the exhaust.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-X322B	CTS	2012-2013	24
ABA-X322C	CTS	2010-2013	662
		TOTAL	686