

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 1 0 2	DATE	Aug.31.2017
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In conversion vans, due to inappropriate instruction of the fastening position on the chassis frame when the cargo compartment is installed, the fastening on the chassis frame for the front side of the cargo compartment was carried out at the different position against design intention.</p> <p>Therefore when the large force to anchor bolt of the front wheel suspension is applied by the compartment movement while the driving and if the vehicle continues to be driven in this condition, the bolt might be broken and the vehicle posture changes, and the fuel tank might be damaged by a part of the bolt, in an extreme case, fuel might leak.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-SQ2F24	N I S S A N A T L A S	2 0 0 7 ~ 2 0 1 7	2 8 8
CBF-SQ1F24			2
PDG-SZ2F24 PKG-SZ2F24 SKG-SZ2F24 TKG-SZ2F24			5 1 2
PDG-SZ1F24 SKG-SZ1F24 TKG-SZ1F24			4
PDG-SZ5F24 PKG-SZ5F24 SDG-SZ5F24 TKG-SZ5F24			9 1
PDG-TZ2F24 PKG-TZ2F24 SKG-TZ2F24			4 3 0
PDG-TZ3F24 PKG-TZ3F24 SKG-TZ3F24			6 0

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
SKG-BSZ2F24 TKG-BSZ2F24	MITSUBISHI FUSO CANTER	2013~2017	29
SKG-BSZ1F24 TKG-BSZ1F24			2
SDG-BSZ5F24			3
PDG-NSZ2F24	UD TRUCKS/ NISSAN DIESEL CONDOR	2007~2013	1
PDG-NSZ5F24 PKG-NSZ5F24			2
PDG-NTZ2F24 PKG-NTZ2F24			3
PDG-NTZ3F24 PKG-NTZ3F24 SKG-UTZ3F24			7
CBF-ASQ2F24	ISUZU ELF	2008~2013	4
PDG-ASZ1F24			1
SDG-ASZ5F24			1
		TOTAL	1,440