

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2528	DATE	09.01.2017
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	FIELD SERVICE ACTION: Certain 2014-15 Model Year EcoSport. -BCM (Body Control) Module Reprogram. Vehicles have been built with a Drive Away Locking personalization feature enabled, which does not comply with ECE 94 regulation. In some cases, BCM reprogramming did not fully disable the Drive Away Locking Feature. To resolve this, dealers are to reprogram the IPC first, then reprogram the BCM.		

TYPE	COMMERCIAL NAME	MODEL YEAR FIELD SERVICE ACTION	NUMBER OF VEHICLE
ABA-MAJUEJ	EcoSport	2014-2015	224 units
TOTAL			224 units