

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	GAI-2531	DATE	1st Sep 2017
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K.)		
DESCRIPTION OF DEFECT	The hazard warning lamps wiring may not be of the correct length and can become damaged during steering operations. This may cause the hazard lamps not to work but will not affect the individual direction indicators.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-GJ900	Street Cup	2017-2018	90
		TOTAL	90