

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4098	DATE	September 7,2017
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate painting for the metal bracket for the speaker of the vehicle access alert device to be installed in the vehicle, the bracket may be rusted in an early stage. As a result, if use continues under the condition, the bracket may brake as the rust progresses causing the speaker to come off and become an obstacle to the traffic.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-U67V	「MINICAB-MiEV」	2011~2012	4,833
ZAB-U68V		2013~2017	1,713
ZAB-U68T		2013~2016	1,036
		TOTAL	7,582