VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2538	DATE	Sep. 14 2017			
MANUFACTURER	Mercedes-Benz (Japanese importer : Mitsubishi Fuso Truck and Bus Corporation)					
DESCRIPTION OF DEFECT	Regarding the door of articulated buses, since the control program of the passenger entrapment prevention device is inappropriate, the pressure sensor may not function when the door comes to an emergency stop. Therefore, the entrapment prevention device may not operate immediately after the door is emergently stopped. In the worst case, a passenger may be trapped in the door.					

ТҮРЕ	COMMERCIAL NAME		MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unclear model	「Citaro-G」	2007~2009		14
		TOTAL	14	