


## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-2529	DATE	Sep. 20, 2017
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer : DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	<p>Ducati Motor Holding production have installed incorrect rear brake reserve tank hose for the involved bikes by mistake. The hose with a wrong material instead the correct material. If the wrong hose is installed, the hose could cause a slight brake fluid seepage itself. And it will possibility to brake fluid seepage and leakage.</p> <p>An official Ducati dealer will replace the reserve tank hose to correct one. This will be performed free of charge.</p> <p>To identify evidence of rear brake reserve tank hose replaced, red mark painted on the hose.</p>		
			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-KB01	Scrambler DESERT SLED	2017	17
		TOTAL	17