

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2512	DATE	September 27, 2017
MANUFACTURE	Aston Martin Lagonda Limited		
DESCRIPTION OF DEFECT	In certain DB11 vehicles, the Electric Control Module for the tyre pressure monitoring system (TPMS) has been incorrectly programmed to a lower pressure than required for warning. This doesn't meet UNECE 64.02 requirements. Because of this, the driver may not be aware that one or more tyres are low.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-AM501	DB11	2016 - 2017	123
		TOTAL	123