VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

CAMPAIGN No.	4117	DATE	September 27, 2017		
MANUFACTURER	KOBELCO CONSTRUCTION MACHINERY CO., LTD				
DESCRIPTION OF	With regard to an engine for wheel crane, inserting process				
DEFECT	of connecting rod bush had been improper. So these bushes				
	which produced under improper process may have not fixed				
	enough.				
	Therefore, in the worst case, the engine would be damaged				
	and the machine	would not be able	to drive when the		
	machine was continued to use without repair.				

TYPE	COMMERCIAL	MODEL YEAR		NUMBER OF
	NAME	RECALLED		VEHICLE
JDS-EE02	RK250-7	2010-2011		16 units
CM02	MK500-2	2011		1 unit
			TOTAL	17