

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2545	DATE	2017/9/28
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain smart fortwo and smart forfour vehicles (453 platform) the left front axle steering knuckle might not meet the specifications due to cavities, which might have been caused by deviations in the casting process of the supplier. These cavities could potentially reduce the strength of the steering knuckle. As a result, in case of increased load, e.g. while parking the vehicle, the left front axle steering knuckle might break.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-453042	smart forfour	2017	2
DBA-453044	smart forfour turbo	2017	1
ABA-453062	smart forfour BRABUS	2017	26
DBA-453344	smart fortwo turbo	2017	4
ABA-453362	smart fortwo BRABUS	2017	1
TOTAL			34