

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4123	DATE	2017/10/5
MANUFACTURER	Shinmaywa Industries, Ltd		
DESCRIPTION OF DEFECT	Due to improper procedure, stay of 3-piece type rear under protection device, hereinafter called "RUPD", was mounted on wrong position. When providing a test load, deformation of RUPD exceeds and becomes non-conformance to safety regulations for road vehicles.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG - CVR77A	ISUZU GIGA	2012	1
QKG - CYJ77A		2015	1
QKG - CYJ77AA		2012~2015	2
QKG - CYJ77B		2016	2
QKG - CYL77AZ		2014	1
QKG - CYY77AY		2012~2015	9
QKG - CYY77BY		2016~2017	7
QPG - CYJ77B		2016	1
QPG - CYY77BY		2016	1
TKG - FK65FY	FUSO FIGHTER	2014~2016	4
BDG - FS54JZ	FUSO SUPER GREAT	2015	1
QKG - FS54VY		2013	1
QKG - FS54VZ		2012~2014	9
QKG - FS55VY		2012	2
QKG - FS55VZ		2012~2014	4
QPG - FS64VZ		2015~2017	5
QPG - FS65VZ		2015	2
QPG - FU64VZ		2017	1
QPG - FY64VY		2016	1
LDG - GK8JNAA	HINO RANGER	2015~2016	4
LKG - FW1EWBA	HINO PROFIA	2012~2015	11
LKG - FW1EXBG		2013	1
QKG - FH1ATAA		2012	1
QKG - FQ1EWBG		2013~2015	6
QKG - FW1EWBA		2012~2014	23
QKG - FW1EWEA		2014~2015	2
QKG - FW1EXBG		2013	1
QKG - FW1EXBJ		2012	1
QKG - FW1EYBJ		2013	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QPG - FQ1EWEG	HINO PROFIA	2015	1
QPG - FQ1EWEJ		2016~2017	3
QPG - FW1EWEA		2015~2016	8
QPG - FW1EXEG		2014~2017	10
QPG - FW1EXEJ		2014~2016	11
QPG - FW1EYEJ		2015	1
QKG - PK39LH		UD TRUCKS Condor	2015
QKG - CG5ZA	UD TRUCKS Quon	2012~2017	5
QKG - CX5YA		2014~2015	2
		TOTAL	148