

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	Gai-2548	DATE	2017/10/11
MANUFACTURE	MASSEY FERGUSON SA (Japanese Importer :MSK Farm Machinery Corporation CEO Toshiki Sugino )		
DESCRIPTION OF DEFECT	The screw holes on the rear axle shaft may have incorrect machining.  In the worst case, the final drive unit may be detached from the axle shaft, and the vehicle may become unable to drive when the lateral pressure is large on the axle shat.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-SU66A	MF7716-4	2016	1
		TOTAL	1