VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2550	DATE	October 20 2017	
MANUFACTURE	FCA US LLC			
	(Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)			
DESCRIPTION OF DEFECT	The front impact sensor wire(s) may become detached during a crash event before the "impact signal" is recorded by the Occupant Restraint Controller (ORC). Vehicles may experience no airbag and or pretensioner deployment in certain crash events where airbag or pretensioner deployment is expected. Failure to deploy the airbags or pretensioners when required during a crash event could increase the risk of injury or death to front seat occupants.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-JK36L	「Wrangler Unlimited」	2016	3,165
ABA-JK36LR	「Wrangler Unlimited」	2016	151
ABA-JK36S	「Wrangler」	2016	136
		TOTAL	3,452