

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2559	DATE	November 8 th , 2017
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate manufacturing of the rear reflector, the required reflection value might not be reached, which does not meet the Japanese Safety Regulation Article 38.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-FW20	BMW 523d	2013	183
DBA-XG20	BMW 523i	2013	230
DBA-XG28	BMW 528i	2013	55
DBA-FR35	BMW 535i	2013	12
DAA-FZ35	BMW ActiveHybrid5	2013	47
ABA-FR44	BMW 550i	2013	2
		TOTAL	529