## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	4140	DATE	Nov.15.2017
MANUFACTURER	ТОУОТА		
DESCRIPTION OF DEFECT	In the battery for driving of the Plug-in hybrid vehicles, due to inadequate capacity of the EV fuse that is designed to protect the hybrid system from potential damage, there is a possibility that the fuse could develop a fatigue fracture if the vehicle is repeatedly operated under high-load driving conditions. If this were to occur, the warning lights would illuminate and, in the worst case, the hybrid system could shut down resulting in the vehicle stopping.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-ZVW35	[PRIUS PHV]	2011-2015	20,442
		TOTAL	20,442