

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4147	DATE	Nov. 20. 2017
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	Due to improper design of outer diameter of the collar between both sides of the rear wheel bearings, the collar may touch with inner side of the wheel collar cover. It may cause adhesion of the collar and the wheel collar cover and may result breakage of the wheel collar cover.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BL-ZR900C	Z900RS	2018	8	
		TOTAL	8	