

## Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

|                       |   |      |               |
|-----------------------|---|------|---------------|
| Campaign No.          | Gai – 2571  | Date | Nov. 29, 2017 |
| Manufacturer          | Jaguar Land Rover Limited<br>( Japanese Importer : Jaguar Land Rover Japan Limited )  |      |               |
| Description of defect | A non-compliance concern has been identified on 2015MY and 2016MY Land Rover Discovery Sport vehicles where the rear licence plate lamp housing may lose retention within the tailgate finisher and subsequently fall out. Should the rear licence plate housing fall out, the rear number plate will not be illuminated as required by regulation. |      |               |

| Type     | Commercial name   | Model year recalled | Number of vehicles |
|----------|-------------------|---------------------|--------------------|
| CBA-LC2A | 「Discovery Sport」 | 2015 - 2016         | 719                |
| Total    |                   |                     | 719                |