

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4 1 5 0	DATE	N o v . 3 0 . 2 0 1 7
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the right/left rear view mirrors, due to an inappropriate manufacturing of the stay, the dimensions of some rear view mirrors at the tightening area may be smaller than the specified dimensions. Therefore, the holding power of the stay becomes insufficient, causing the stay to turn because of wind pressure while running, etc. As a result, the traffic to the rear may not be checkable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2 B L - R M 2 2 J	X S R 7 0 0	2 0 1 7	2 3 6
		TOTAL	2 3 6