

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4173	DATE	Jan.17.2018
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the front passenger dual-stage airbag inflator of the subject vehicles, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could degrade after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture in the event the airbag is activated.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
DBA-GSE20	[IS250]	2013	67	
DBA-GSE25			11	
DBA-GSE20	[IS250C]		251	
DBA-GSE21	[IS350]		10	
	[IS350C]		104	
DBA-USE20	[IS F]		122	
			TOTAL	565