

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	4171	DATE	January 18, 2018
MANUFACTURER	HITACHI CONSTRUCTION MACHINERY CO.,LTD (JAPAN)		
DESCRIPTION OF DEFECT	<p>Shovel loader 「ZX125W-6」is subject to a recall due to motor safety concern since its oil cartridge assemble instruction was incorrect and assembly was compromised. As a result, oil cartridge tightening torque is too low and this could cause oil filter cartridge loosen in constant vibration in driving.</p> <p>Therefore if no measure is taken, this could result in engine oil leakage, warning sign activation and, at worst case scenario, an engine seizure.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
YDR-LADA	ZX125W-6	2017	36	
		TOTAL	36	