

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4178	DATE	January.18. 2018
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In certain the passenger's airbag inflators, gas generating propellant may get deteriorated through repetition of environmental temperature and humidity fluctuations. This can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator whereby the container of inflator could be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GB3	「FREED」 「FREED SPIKE」	2013	21,403
DBA-GB4			4,050
DAA-GP3			24,073
DBA-GE6	「FIT」		22,372
DBA-GE7			4,232
DBA-GE8			1,740
DBA-GE9			432
DAA-GP1			9,810
DAA-GP4			921
DAA-GP2	「FIT SHUTTLE」		15,004
DBA-GG7			3,350
DBA-GG8			1,568
DAA-ZE2	「INSIGHT」		1,818
DAA-ZE3	「INSIGHT EXCLUSIVE」	1,337	
DBA-RR1	「ELYSION PRESTAGE」	282	
DBA-RR2		65	
DBA-RR5		214	
DBA-RR6		64	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
DBA-CU1	「ACCORD」	2013	181	
DBA-CU2			89	
DBA-CW1	「ACCORD TOURER」		120	
DBA-CW2			143	
ZAA-ZA2	「FIT EV」		90	
ZBA-ZC3	「FCX CLARITY」		4	
			TOTAL	113,362