

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2584	Date	January 24, 2018
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper design of the high pressure pump in fuel system, airtightness between the valve for adjusting the fuel and the pump housing is insufficient. As a result, the fuel pressure in the pump increases at a high speed running or the like, and the fuel might leak from the fuel pressure regulating valve position.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-AUCHH	VW Golf GTI	MY2014-2015	3,296
ABA-AUCJXF	VW Golf R	MY2014-2015	724
		Total	4,020