

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4180	DATE	Jan. 25,2018
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>The slide door structure of the cargo compartment on freezer car and cooler car is improper at the upper slide. When the slide door is closed with a strong force, the upper roller may fall off and abnormal noise occurs. If a vehicle with this condition is used continuously, the roller bracket pin comes off the upper rail and the slide door may not close in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-S500P	HIJET TRUCK	2016-2017	222
EBD-S510P			76
		TOTAL	298