

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2586	DATE	January 29 th , 2018
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to an inappropriate software in the instrument cluster, the display of the instrument cluster can completely fail when starting the vehicle. Thus, speed meter and indicator etc. might not be displayed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-1R15	BMW 118i	2017	1,014
DBA-1S20G	BMW 120i	2017	5
LDA-1S20	BMW 118d	2017	933
DBA-1S30	BMW M140i	2017	10
DBA-2F20	BMW 220i	2017	120
DBA-2G30	BMW M240i	2017	62
ABA-2G30G		2017	15
CBA-1H30G	BMW M2	2017	216
		TOTAL	2,375