

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4188	DATE	Feb. 8, 2018
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Subaru identified instances where the final vehicle inspection in the vehicle assembly plants was being performed by person(s) who had promoted to "final vehicle inspector" without predetermined education. Therefore, the inspection related to the Japanese Safety Regulation under the Japan's Road Transport Vehicle Act was not performed appropriately.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-VM4	「LEVORG」	2017	3,805
DBA-VMG		2017	1,040
DBA-VAG	「WRX」	2017	1,019
CBA-VAB		2017	798
DBA-GK2	「IMPREZA」	2017	286
DBA-GK3		2017	196
DBA-GK6		2017	511
DBA-GK7		2017	784
DBA-GT2		2017	1,863
DBA-GT3		2017	1,228
DBA-GT6		2017	1,390
DBA-GT7		2017	2,062
DBA-GT3	「XV」	2017	1,034
DBA-GT7		2017	3,003
DBA-SJ5	「FORESTER」	2017	2,332
DBA-SJG		2017	449
DBA-BN9	「LEGACY」	2017	642
DBA-BS9		2017	2,457
DBA-YAM	「EXIGA」	2017	573
DBA-ZC6	「BRZ」	2017	507
DBA-ZN6	「86」	2017	1,087
		TOTAL	27,066