

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4193	DATE	February 8,2018
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>On certain front wipers, water may go through the gap between the front deck garnish and the windshield glass due to the improper waterproof structure on the front deck area. The water may intrude into the joint portion between the wiper motor and the wiper linkage. As a result, the inside of the joint portion may be corroded and may cause the abnormal wear. In the worst case, there is a risk that the joint portion between the wiper motor and the wiper linkage may come off and the wiper may stop operating.</p>		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GA3W	「RVR」	2010～2012	18,273
DBA-GA4W		2011～2016	13,755
		TOTAL	32,028