VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2596	DATE	February 20 2018	
MANUFACTURE	FCA US LLC			
	(Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)			
DESCRIPTION OF DEFECT	The Occupant Restraint Control (ORC) module may experience a malfunction due to corrosion of the power supply integrated circuit. This could result in an illuminated airbag warning lamp with the possibility of no airbag deployment in a crash necessitating airbag deployment or an inadvertent airbag deployment without an illuminated airbag warning lamp. Either of these conditions could increase the risk of a crash and/or injury to front seat vehicle occupants.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-RT38	「Grand Voyager」	2008–2009	53
ABA-JC27	LACI	2009	57
Unkown	LACT	2009	1
		TOTAL	111