

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	4 1 9 4	DATE	Feb. 23. 2018
MANUFACTURER	Nichijo Manufacturing Co.,Ltd.		
DESCRIPTION OF DEFECT	<p>In the transmission of the rotary snow plow, The installation location of the controller is inappropriate. Due to the influence of heat from the heater, the vehicle traveling control substrate becomes high temperature.The DC - DC converter may not operate normally.</p> <p>For that reason,The power supply of the operational amplifier which controls the increase / decrease of the vehicle speed according to the position of the forward / reverse lever is cut off. Speed control becomes impossible. In the worst case, There is a risk of starting at an unintended speed.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-R03E	「HTR308」	2016~2018 R03E-0001~ R03E-0105	94
YDS-R06E	「HTR408」	2016~2017 R06E-0001~ R06E-0019	14
YDS-R01E	「HTR608」	2016~2017 R01E-0001~ R01E-0011	6
TOTAL			114

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.