

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2600	DATE	February 28, 2018
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>It is possible that a fault in an earth connection on the ESC control unit may occur due to excessive thermo-mechanical strain on components in the control unit. In this case, fault-free operation of the control unit can no longer be assured.</p> <p>A software update of the ESC control unit must be carried out on the vehicles affected.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8PCAX	A3 1.4 TFSI	2009	1,765
ABA-8PCCZF	A3 2.0 Tq		684
ABA-8PCDA	A3 1.8 T		793
ABA-8PCDLF	S3		223
		Total	3,465