

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2601	DATE	February 28, 2018
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>The auxiliary heater element in the air conditioner may fail. In rare cases, this may lead to smoulder damage or even fire.</p> <p>The heater element must be replaced and the software on the air conditioner control unit must be updated on the affected vehicles.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-8RCHJF	Q5 Hybrid	2013-2015	168
		Total	168