

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 2602	Date	February, 28, 2018
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	<p>Autoliv, in their defect information report relating to the AI2 initiator, reported that deviations can occur in the generant mix ratio in some initiators manufactured by an Autoliv Group company. These initiators have been used in the manufacture of Autoliv seat belt pre-tensioners supplied to Jaguar Land Rover Limited. Autoliv go on to report that if the generant mix ratio does not meet specification, the initiator may not properly function leading to no activation of a pre-tensioner.</p> <p>In the event of a crash of sufficient severity, the front seatbelt pre-tensioner may fail to operate when required. Failure to operate can lead to increased injuries to the front seat occupants.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
LDA-JA2NA	「XE」	2017	228
CBA-JA2GA	「XE」	2017	27
CBA-JA3VA	「XE」	2017	10
CBA-J608A	「F-TYPE」	2017	37
CBA-J60MA	「F-TYPE」	2017	17
Total			319