

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 2603	Date	February, 28, 2018
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	<p>Autoliv, in their defect information report relating to the AI2 initiator, reported that deviations can occur in the generant mix ratio in some initiators manufactured by an Autoliv Group company. These initiators have been used in the manufacture of Autoliv seat belt pre-tensioners supplied to Jaguar Land Rover Limited. Autoliv go on to report that if the generant mix ratio does not meet specification, the initiator may not properly function leading to no activation of a pre-tensioner.</p> <p>In the event of a crash of sufficient severity, the front seatbelt pre-tensioner may fail to operate when required. Failure to operate can lead to increased injuries to the front seat occupants.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
ABA-LW3SA	「Range Rover」	2016	19
ABA-LW5SA	「Range Rover Sport」	2016	11
CBA-LC2A	「Discovery Sport」	2017	169
Total			199