

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

| | | | |
|-----------------------|---|------|--------------------|
| Campaign No. | Gai – 2604 | Date | February, 28, 2018 |
| Manufacturer | Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited) | | |
| Description of defect | <p>On certain 2016 MY Range Rover and Range Rover Sport vehicles, the front passenger airbag may not function properly due to a deviation in generant mix ratio.</p> <p>In the event of a crash of sufficient severity, the front passenger airbag may not deploy when required. Failure to deploy can lead to increased injuries to the passenger seat occupant.</p> | | |

| Type | Commercial name | Model year recalled | Number of vehicles |
|-----------|---------------------|---------------------|--------------------|
| ABA-LG5SA | 「Range Rover」 | 2016 | 1 |
| ABA-LW3SA | 「Range Rover Sport」 | 2016 | 1 |
| Total | | | 2 |