

## Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 2605	Date	February, 28, 2018
Manufacturer	Jaguar Land Rover Limited ( Japanese Importer : Jaguar Land Rover Japan Limited )		
Description of defect	<p>Jaguar Land Rover has identified a concern with diesel engine Jaguar XE and XF 2016 and certain 2017 Model Year vehicles where the under bonnet low pressure fuel feed hose may detach from the fuel filter. A fuel smell may be noticed due to fuel leaking into the engine bay and, in the event of hose detachment, the engine will cut out. Once the engine has cut out, the brake vacuum reservoir will be depleted after 2-3 brake pedal depressions and the vehicle will lose brake power assistance, however foundation brakes continue to operate. The engine cannot be re-started.</p> <p>Engine cut out with minimal warning could potentially cause a crash.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
LDA-JA2NA	「XE」	2016-2017	304
LDA-JB2NA	「XF」	2016-2017	66
Total			370