

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2594	DATE	March 7th, 2018
MANUFACTURE	MV AGUSTA (Japanese importer: MV AGUSTA JAPAN CO., LTD.)		
DESCRIPTION OF DEFECT	Spoke's tightening force is insufficient on some motorcycles because the rear wheel production is not appropriate. For the reason, if it is keep using as it is, it may cause the spokes to loose by running vibration, the rear wheel is shaken, in the worst case, it may cause motorcycles to lose the running stability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZCGB322	Brutale 800 Dragster RR	2017	15
		TOTAL	15