

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2619	DATE	March 08 2018
MANUFACTURE	FCA US LLC (Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)		
DESCRIPTION OF DEFECT	Some vehicles equipped with EHPS may experience an alternator diode thermal fatigue failure due to cyclical loads induced by EHPS. This failure could occur with warning. When the diodes fail, the alternator will no longer supply electrical energy to the vehicle and may lead to a vehicle stall with warning. Failed diodes may also develop a resistive short circuit that can result in heat and/or smoke originating within the alternator.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-WK36	「Jeep・Grand Cherokee」	2012-2013	1507
ABA-WK36A	「Jeep・Grand Cherokee」	2012-2013	1028
ABA-LX36	「300」	2012-2013	1396
		TOTAL	3931