

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-2618	DATE	Mar. 9, 2018
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer : DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	<p>In the front brake, the design of the master cylinder is inappropriate, and some of the pistons in the cylinder are insufficient in strength. Therefore, if the piston is cracked due to the brake fluid pressure at the time of brake operation and the use continues in this state, cracks will develop and the piston will be damaged, and in the worst case the front brake may become ineffective.</p> <p>The official Ducati dealer will replace the master cylinder piston with a modified part. This will be performed free of charge</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-HC00	1299 Superleggera 1299 Panigale R Final Edition	2017-2018	51
2BL-KB01	Scrambler Café Racer	2018	70
2BL-MA02	Monster 1200S	2017-2018	77
EBL-AA02	Multistrada 1200S Multistrada 1200PikesPeak	2015-2017	332
EBL-GA01	XDiavel S	2016	190
EBL-MA01	Monster 1200R	2016-2017	180
ZDMH902JAFB	Panigale R	2015-2016	50
ZDMH902JAGB	Panigale R	2016-2017	14
ZDMH905JAFB	1299 Panigale 1299 Panigale S	2015-2016	322
ZDMM603JAFB	Monster 1200S Monster 1200S Stripe	2015-2016	112
		TOTAL	1398