

## Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai- 2621	Date	March, 14, 2018
Manufacturer	Jaguar Land Rover Limited ( Japanese Importer : Jaguar Land Rover Japan Limited )		
Description of defect	<p>Jaguar Land Rover has identified a concern with certain 2015 Model Year (MY) Range Rover and Range Rover Sport vehicles installed with the manual recline second row seat system where the second row seat backrest may not latch robustly in position.</p> <p>It is possible the visual indication of correct latch (the operating lever) condition is false and misleading and as such, especially in the centre second row seated position, the seat belt may not correctly restrain the occupant during a crash which increases the risk of injury.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
ABA-LW3SA	「Range Rover Sport」	2015	8
ABA-LG3SB	「Range Rover」	2015	3
ABA-LG5SA	「Range Rover」	2015	2
<b>Total</b>			<b>13</b>