

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2613	DATE	March 16, 2018
MANUFACTURER	General Motors LLC		
DESCRIPTION OF DEFECT	The light output of the forward position lamps is above design intent. The electrical circuit in the position lamp's electronic control unit was designed incorrectly, leading to the position lamp's electronic control unit to misinterpret the signals from the vehicle's body control module. This results in higher than expected light output.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-O1SL	CT6	2016 - 2017	69
		TOTAL	69