

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-2615	DATE	March 16, 2018
MANUFACTURE	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	In the front left side axle carrier. A mistake during the casting process has resulted in the production of front left sub axle carriers with internal defaults. There are risk of degradation of the front left axle carrier durability according to the driver' s use and road profile, vehicle may cannot steer or cannot running if axle carrier broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-AHDH	「TWINGO」	2017	3
DBA-AHH4B			11
		TOTAL	14